

1 Photographic Feature

2

3 **Strike-slip ground-surface rupture (Greendale Fault) associated with the 4th**

4 **September 2010 Darfield Earthquake, Canterbury, New Zealand**

5

6 D.J.A. Barrell^{1,*}, N.J. Litchfield², D.B. Townsend², M. Quigley³, R.J. Van Dissen², R.

7 Cosgrove⁴, S.C. Cox¹, K. Furlong⁵, P. Villamor², J.G. Begg², S. Hemmings-Sykes², R.

8 Jongens¹, H. Mackenzie³, D. Noble³, T. Stahl³, E. Bilderback³, B. Duffy³, H. Henham³,

9 A. Klahn³, E.M.W. Lang¹, L. Moody³, R. Nicol³, K. Pedley³, A. Smith³

10

11 ¹GNS Science, Dunedin, New Zealand; ²GNS Science, Lower Hutt, New Zealand;

12 ³Dept. of Geological Sciences, University of Canterbury, New Zealand; ⁴The Press,

13 Christchurch, New Zealand; ⁵Dept. of Geosciences, Penn State University, USA

14 * Corresponding author (d.barrell@gns.cri.nz)

15

16 **Abstract:** This paper provides a photographic tour of the ground-surface rupture

17 features of the Greendale Fault, formed during the 4th September 2010 Darfield

18 Earthquake. The fault, previously unknown, produced at least 29.5 km of strike-slip

19 surface deformation of right-lateral (dextral) sense. Deformation, spread over a zone

20 between 30 and 300 m wide, consisted mostly of horizontal flexure with subsidiary

21 discrete shears, the latter only prominent where overall displacement across the zone

22 exceeded about 1.5 m. A remarkable feature of this event was its location in an

23 intensively farmed landscape, where a multitude of straight markers, such as fences,

24 roads and ditches, allowed precise measurements of offsets, and permitted well-defined

25 limits to be placed on the length and widths of the surface rupture deformation.

26 **Introduction**

27

28 The M_w 7.1 Darfield Earthquake, centred about 40 km west of the city of Christchurch,
29 New Zealand, struck at 4:35 am on 4th September 2010, shattering the pre-dawn
30 darkness with a deafening roar and violent shaking. The rising sun illuminated a newly
31 formed fault trace, aligned roughly west-east across farmland of the Canterbury Plains
32 (Fig. 1). The earthquake created very strong, damaging, ground motions in the
33 Canterbury region and was felt through much of New Zealand (Cousins & McVerry
34 2010; Gledhill *et al.* 2010, 2011). Fortunately, there were no fatal injuries and only two
35 people were reported to have been seriously injured. However, damage to building
36 contents, building structures, roads and utilities, particularly in low-lying coastal areas
37 where liquefaction was severe (Cubrinovski *et al.* 2010), was assessed as being likely to
38 run to several billion New Zealand dollars. Circumstances changed tragically on 22nd
39 February 2011, when a shallow-focus aftershock of M_w 6.3 struck 10 km southeast of
40 the Christchurch city centre (Reyners 2011). The Christchurch Earthquake caused much
41 more severe damage to the city than did the Darfield Earthquake, with the loss of about
42 182 lives, many injuries, and serious social and economic disruption. However, the
43 focus of this paper is confined to the Greendale Fault surface rupture (Fig. 1) formed in
44 the 4th September 2010 Darfield Earthquake.

45

46 **Discovery**

47

48 Within three hours of the earthquake, a fault rupture reconnaissance and response team
49 had been deployed, led by scientists from University of Canterbury Department of
50 Geological Sciences (UC) and from GNS Science (GNS), New Zealand's government-

owned earth science research institution. Fanning out towards the epicentre, the locally-based UC team had, about 5 hours after the earthquake, located evidence for ground-surface fault rupture and began examining and measuring the rupture zone, and assessing associated hazards to the affected community. Upon arrival in the region, about 8 hours after the earthquake, GNS scientists took a helicopter reconnaissance flight and established that at least 16 km of surface rupture were visible from about 200 m altitude. Within 36 hours of the earthquake, ground-based reconnaissance had established a surface rupture length of about 22 km. Over the following two weeks, detailed mapping extended this by a further 7.5 km, to a total of approximately 29.5 km (Fig. 1) (Quigley *et al.* 2010a, 2010b; Van Dissen *et al.* 2011).

Setting

Named after the hamlet of Greendale near the western end of the fault (Fig. 1), the predominantly strike-slip ground surface rupturing fault, with a right-lateral (dextral) sense of displacement, traversed gravelly alluvial plains. The surface of this sector of the Canterbury Plains dates from the end of the Last Glaciation, with post-glacial incised degradation terraces adjacent to active river channels (Forsyth *et al.* 2008). Relict, generally subtle, river channel and bar patterns on the plains are thoroughly overwhelmed by the human geomorphological footprint, comprising a matrix of straight linear features such as fences, roads, power lines, crop rows and irrigation ditches. Along the full length of the surface trace, rarely is there a stretch of more than 300 m without a human-made (formerly) straight line.

75 The boundary between the Australian and Pacific plates bisects New Zealand (Fig. 1a).
76 The Pacific plate is moving west-southwest relative to the Australian plate, at 48 mm/yr
77 in northeastern New Zealand, decreasing to 39 mm/yr in the southwest (Wallace *et al.*
78 2007). Between the Puysegur and Hikurangi subduction thrusts, the oblique dextral
79 strike-slip/reverse Alpine Fault is the locus of plate boundary movement in the South
80 Island. A small portion of the plate motion is accommodated by a broad zone of active
81 deformation southeast of the Alpine Fault, with many active faults and folds (Fig. 1b).
82 The Greendale Fault lies near the southeast margin of this deformation zone. No prior
83 indication had been found of a fault at this location. Regional geological mapping of
84 this region in the mid-2000s had not found any surface evidence of a fault scarp on this
85 part of the Canterbury Plains (Forsyth *et al.* 2008), although the field work was
86 generally limited to drive-by reconnaissance.

87

88 Also adding to the surprise of the emergence of the Greendale Fault was that this part of
89 Canterbury has had only a low level of historical seismicity (Stirling *et al.* 2008).

90

91 **Description**

92

93 The westernmost ~6 km of the surface trace has a northwest strike and displays oblique
94 dextral and south-side-up vertical displacement (net) of as much as 1.5 m (Figs. 2 and
95 3). Movement was accommodated by ground flexure, with few, if any, surface shears.
96 Net upthrow to the south caused partial avulsion of the Hororata River, although this
97 was rectified within a few days by deepening of the natural channel using excavators.

98

99 In the central ~15 km of the surface trace, displacement exceeds ~2.5 m, expressed on
100 left-stepping, en echelon traces (Figs. 5 to 18). Deformation is distributed across a 30 to
101 300 m wide zone, mainly via horizontal flexure but with discrete Riedel shears and
102 conjugate Riedel shears. Along the central 8 km of surface rupture, lateral displacement
103 exceeds 4 m and the fault trace was obvious to even the untrained eye, with roads and
104 fences bent and sheared sideways by as much as 5 m (see Figs. 5 to 14).

105

106 Towards the east, the deformation stepped about 1 km to the north, forming a separate
107 trace, which represents the easternmost ~6 km of the fault (see Fig. 1). On this eastern
108 trace, dextral displacement is no more than about 1.5 m, virtually all accommodated by
109 horizontal flexure (Figs. 19 to 21).

110

111 Vertical displacement is most prominent at the western end of the fault (see above).
112 Elsewhere, the overall vertical component is rarely more than 0.5 m, but with localized
113 push-ups, of as much as 1.5 m, formed at most of the numerous en echelon left-steps.
114 The south side is up everywhere except at the eastern end of the fault, which is north
115 side up. The scale of vertical deformation is comparable to the natural relief of fluvial
116 landforms on the Canterbury Plains. For most of the length of the fault, without the
117 broken ground (e.g. mole tracks – displaced turf) or linear markers such as fences, the
118 fault would not have been readily discernable, and will become less so over time, as
119 fissures fill and bumps smooth over.

120

121 In many of the photographs in this paper, red arrows are used to denote the approximate
122 position and strike of the fault trace.

123

124 **Summary**

125

126 Perhaps the most remarkable feature of this strike-slip ground surface rupture is that it
127 occurred within a landscape containing a myriad of straight lines. These provided
128 perfect ‘piercing points’ for measuring the amounts and styles of fault deformation.
129 Moreover, these straight lines made it easy to see deformation features as subtle as 1 m
130 horizontal flexures of the ground that were several tens of metres wide, which were not
131 even accompanied by discernable cracking of the ground surface. As a result, it was
132 possible to document the character and extent of the Greendale Fault, as revealed during
133 the 4th September 2010 Darfield Earthquake, to a spectacular level of precision.

134

135 **Acknowledgements.** We express our gratitude to landowners in the area of the fault
136 rupture for kindly allowing access to their properties during the stressful period
137 following the earthquake, and its numerous aftershocks.

138

139 This work was carried out with funding assistance from a variety of sources, including
140 the Earthquake Commission via the Geonet Project, and the Foundation for Research,
141 Science and Technology (now Ministry of Science and Innovation) through the New
142 Zealand Natural Hazards Research Platform and the Geological Map of New Zealand
143 programme. We thank Grant Dellow and Brenda Rosser (both GNS Science), and an
144 anonymous journal reviewer, for their reviews of the manuscript.

145

146 Photo credits: DB, Figs. 2a, 2b, 11, 14, 19, 21; NL, Figs 4b, 6, 7; DT, Figs. 10a, 16, 17,
147 20; MQ, Fig. 15; RVD, Fig. 3; RC, Figs. 5, 18a; SC, Figs. 4a, 8; KF, Fig. 13; PV, Fig.
148 18b; JB, Fig. 9; SHS/HM, Fig. 10b; TS, Fig. 12.

149

150 **References**

151

152 COUSINS, J. & McVERRY, G. 2010. Overview of strong-motion data from the
153 Darfield earthquake. *Bulletin of the New Zealand Society for Earthquake Engineering*,
154 **43**, 222-227.

155

156 COX, S.C. & BARRELL, D.J.A. (compilers) 2007. *Geology of the Aoraki area*.
157 Institute of Geological and Nuclear Sciences 1:250,000 Geological Map 15. 1 sheet &
158 71 p. Lower Hutt, New Zealand. GNS Science.

159

160 CUBRINOVSKI, M., GREEN, R.A. (editors), ALLEN, J., ASHFORD, S., BOWMAN,
161 E., BRADLEY, B., COX, B., CUBRINOVSKI, M., GREEN, R.A., HUTCHINSON, T.,
162 KAVAZANJIAN, E., ORENSE, R., PENDER, M., QUIGLEY, M., WOTHERSPOON,
163 L. (contributing authors) 2010. Geotechnical reconnaissance of the 2010 Darfield
164 (Canterbury) earthquake. *Bulletin of the New Zealand Society for Earthquake*
165 *Engineering*, **43**, 243-320.

166

167 FORSYTH, P.J., BARRELL, D.J.A. & JONGENS, R. (compilers) 2008. *Geology of the*
168 *Christchurch area*. Institute of Geological and Nuclear Sciences 1:250,000 Geological
169 Map 16. 1 sheet + 67 p. Lower Hutt, New Zealand. GNS Science.

170

171 GLEDHILL, K., RISTAU, J., REYNERS, M., FRY, B. & HOLDEN, C. 2010. The
172 Darfield (Canterbury) M_w 7.1 earthquake of September 2010: preliminary seismological
173 report. *Bulletin of the New Zealand Society for Earthquake Engineering*, **43**, 215-221.

174

175 GLEDHILL, K., RISTAU, J., REYNERS, M., FRY, B. & HOLDEN, C. 2011. The
 176 Darfield (Canterbury, New Zealand) M_w 7.1 earthquake of September 2010: a
 177 preliminary seismological report. *Seismological Research Letters*, **82**, 378-386.

178

179 QUIGLEY, M., VILLAMOR, P., FURLONG, K., BEAVAN, J., VAN DISSEN, R.,
 180 LITCHFIELD, N., STAHL, T., DUFFY, B., BILDERBACK, E., NOBLE, D.,
 181 BARRELL, D., JONGENS, R. & COX, S. 2010a. Previously unknown fault shakes
 182 New Zealand's South Island. *Eos*, **91**, 469-470.

183

184 QUIGLEY, M., VAN DISSEN, R., VILLAMOR, P., LITCHFIELD, N., BARRELL,
 185 D., FURLONG, K., STAHL, T., DUFFY, B., BILDERBACK, E., NOBLE, D.,
 186 TOWNSEND, D., BEGG, J., JONGENS, R., RIES, W., CLARIDGE, J., KLAHN, A.,
 187 MACKENZIE, H., SMITH, A., HORNBLOW, S., NICOL, R., COX, S.,
 188 LANGRIDGE, R. & PEDLEY, K. 2010b. Surface rupture of the Greendale Fault during
 189 the M_w 7.1 Darfield (Canterbury) Earthquake, New Zealand: initial findings. *Bulletin of*
 190 *the New Zealand Society for Earthquake Engineering*, **43**, 236-242.

191

192 REYNERS, M. 2011. Lessons from the destructive M_w 6.3 Christchurch, New Zealand,
 193 Earthquake. *Seismological Research Letters*, **82**, 371-372.

194

195 STIRLING, M., GERSTENBERGER, M., LITCHFIELD, N., MCVERRY, G., SMITH,
 196 W., PETTINGA, J. & BARNES, P. 2008. Seismic hazard of the Canterbury region,
 197 New Zealand: new earthquake source model and methodology. *Bulletin of the New*
 198 *Zealand Society for Earthquake Engineering*, **41**, 51-67.

199

200 VAN DISSEN, R., BARRELL, D., LITCHFIELD, N., VILLAMOR, P., QUIGLEY,
201 M., KING, A., FURLONG, K., BEGG, J., TOWNSEND, D., MACKENZIE, H.,
202 STAHL, T., NOBLE, D., DUFFY, B., BILDERBACK, E., CLARIDGE, J., KLAHN,
203 A., JONGENS, R., COX, S., LANGRIDGE, R., RIES, W., DHAKAL, R., SMITH, A.,
204 HORNBLow, S., NICOL, R., PEDLEY, K., HENHAM, H., HUNTER, R., ZAJAC, A.
205 & MOTE, T. 2011. Surface rupture displacement on the Greendale Fault during the M_w
206 7.1 Darfield (Canterbury) earthquake, New Zealand, and its impact on man-made
207 structures. *In: Proceedings of the 9th Pacific Conference on Earthquake Engineering*,
208 Auckland, New Zealand, 14-16 April, 2011, Paper 186, 8 p.

209

210 WALLACE, L.M., BEAVAN, R.J., MCCAFFREY, R., BERRYMAN, K.R., DENYS,
211 P., 2007. Balancing the plate motion budget in the South Island, New Zealand using
212 GPS, geological and seismological data. *Geophysical Journal International*, **168**, 332-
213 352.

214

215

216 **Fig. 1.** Location and neotectonic setting. **(a)** Bathymetry of the New Zealand region
217 (orange=shallow, blue=deep; image courtesy of GNS Science), annotated with the plate
218 tectonic setting. **(b)** The Greendale Fault in relation to mapped active faults (red) and
219 folds (orange), from Cox & Barrell (2007) and Forsyth et al. (2008), and the Darfield
220 earthquake epicentre (star). **(c)** Generalised map of the Greendale Fault ground surface
221 deformation; the numbers denote the locations of photos in Figures 2 to 21. The map
222 images are derived from NZMS 266 (b) and Topo250 (c) topographic maps of New
223 Zealand, copyright Land Information New Zealand.

224

225 **Fig. 2.** **(a)** The sinuous course of the Hororata River, flowing from upper right to upper
226 left, is crossed by the fault in this westward view, taken 4th September. A significant
227 portion of the river's flow is diverted towards the lower left, along the downthrown side
228 of the fault. **(b)** In this view southeast from location (b) shown in Fig. 2a, taken 15th
229 September, the broad rise up to the right is the fault, which here has bent rather than
230 broken the ground. Excavation of the river channel has stemmed the overflow across
231 farmland.

232

233 **Fig. 3.** This view south along an originally straight fence in a formerly flat field
234 illustrates the oblique right-lateral (~1 m) and up-to-south (~1 m) ground flexure that
235 characterizes the western end of the Greendale Fault.

236

237 **Fig. 4.** **(a)** Progressing eastward, where the horizontal flexure exceeds 2 m, ground
238 cracking became increasingly evident, as seen across the farm lane in this view to the

239 south. **(b)** Detail of the form and depths of tension cracks seen in Fig. 4a, looking
240 northeast, on 5th September.

241

242 **Fig. 5.** This northward aerial view at Stranges Road highlights Reidel shears, at a low
243 angle to the strike of the fault, each with as much as 1 m lateral offset, as seen across the
244 vehicle ruts. However, most of the ~4.5 m right-lateral displacement is by horizontal
245 flexure, as shown by the hedge row and irrigation ditch. Flow in the ditch was impeded
246 by slight upthrow to the south, but the ditch had been deepened prior to this photograph
247 on 9th September.

248

249 **Fig. 6.** At Courtenay Road, this northward view shows team members carrying out a
250 precise Real-Time Kinematic GPS survey of a right-lateral offset (~4.3 m) of the
251 formerly straight fenceline. The deformation occurred over a ~35 m wide zone, and the
252 ground is broken by discrete shears right of centre.

253

254 **Fig. 7.** This view looking south shows the surface fault rupture where most of the lateral
255 displacement (~4.6 m) is concentrated within a narrow zone, with ‘mole tracks’
256 (displaced turf) evident along shears that displace the fenceline.

257

258 **Fig. 8.** An aerial view looking northeast showing en echelon Reidel shears that narrowly
259 miss a house, but pass through its garage.

260

261 **Fig. 9.** In this telephoto view north along Telegraph Road, the busiest road to have been
262 crossed by the fault rupture, the Greendale Fault has displaced the road right-laterally by

263 approximately a lane width. Being a major rural thoroughfare, initial repairs were
264 undertaken on the day of the earthquake.

265

266 **Fig. 10. (a)** A shear with about 0.5 to 1 m of right-lateral displacement passed through
267 this modern, timber-framed, brick-clad farm house. Despite suffering severe structural
268 damage, the house remained standing and its occupants were unharmed. **(b)** A view
269 looking west at the opposite side of the house shown in Fig. 10a.

270

271 **Fig. 11.** A view south down Highfield Road, the second of only two tarsealed roads to
272 have been crossed at a high angle by the fault in its high-displacement central section.
273 Being a minor road, several days passed before repairs were made to the spectacular
274 array of shears and cracks across the tarseal. In the meantime, the site became a local
275 tourist attraction because it was one of the few fault rupture locations that was both
276 undisturbed and publicly accessible. Here, localized bulging resulted in an upthrow of
277 more than 1 m, creating a visual phenomenon in concert with the ~4.5 m right-lateral
278 offset of the carriageway, roadside fences and hedge-rows.

279

280 **Fig. 12.** Members of the fault rupture reconnaissance team measure offsets (~3.6 m) of
281 a fenceline a few hundred metres east of Highfield Road, view looking south.

282

283 **Fig. 13.** This view east along the fault displays a spectacular pattern of conjugate Reidel
284 shears at a high angle to the strike of the fault, which curves off towards the upper left.
285 The fence in the mid-ground is the same one shown in Fig. 12.

286

287 **Fig. 14.** A northward aerial view of a narrow fault zone (left) diffusing into a broad
288 flexure across the ploughed fields, then narrowing into a shear near the crops to the
289 right. Total right-lateral displacement of these features is ~4.5 m.

290

291 **Fig. 15. (a)** Arrays of shears and localized bulges are seen in this aerial view looking
292 north. The irrigation ditch is displaced laterally by ~3.5 m. **(b)** Following initial science
293 reports to the media, stating that there was no prior knowledge of a fault in this area, a
294 landowner ploughed these words into this field. The words reference a nationwide
295 billboard advertising campaign for a brand of beer, in which a bold statement is made,
296 alongside of which are the words ‘yeah, right’, indicating that a sensible person would
297 not believe the statement. The view is southwest, and the features shown in Fig. 15a are
298 upper left from centre.

299

300 **Fig. 16.** A close-up view of shears within a field. Their expressions are particularly
301 clear on account of the very short grass. The total right-lateral displacement at this site
302 is ~3.5 to ~4 m.

303

304 **Fig. 17.** Where shears crossed belts of trees, commonly the trees were loosened from
305 the soil, or uprooted. This was one rare instance where a shear split a tree in two, in this
306 case a juvenile *Pinus radiata* with trunk diameter of ~0.15 m.

307

308 **Fig. 18. (a)** An aerial view north showing shears crossing an irrigation ditch (right-
309 lateral offset of ~2.6 m) and passing through a farm shed. The left-hand side of this
310 building is shown in Fig. 18b. **(b)** Members of the fault rupture reconnaissance team

311 measure the effects of a shear, its mole track evident in the foreground, on the farm
312 shed.

313



314 **Fig. 19.** On the eastern strand of the fault, deformation comprised horizontal flexure,
315 with very little cracking of the ground. For the most part, cracks were evident only
316 where the fault crossed a relatively brittle feature such as a tarsealed road. In this view
317 southward, the fence reveals a right-lateral flexure of about 1.3 m.

318

319 **Fig. 20.** In this view northeastward, the painted centreline of Kerrs Road displays a
320 right-lateral flexure of about 1.5 m. An array of minor cracks formed across the road in
321 the flexure zone. Without straight linear features such as roads and fences, this
322 deformation would be indiscernible.

323

324 **Fig. 21.** Near the eastern limit of recognised deformation, the fault crossed the South
325 Island Midland Railway. This view southward illustrates a broad right-lateral flexure of
326 ~1 m of the line of the rails. As the rail embankment tends to smooth over the minor
327 natural fluvial irregularities of the plains, the rails were an excellent datum for
328 estimating the vertical component of offset. Precise GPS surveying indicated
329 approximately 0.4 m of upthrow to the north at this location. During the earthquake, one
330 section of the rails was kinked sideways to the left (east). This photograph was taken on
331 5th September, immediately after replacement of the kinked rail section. The new rails
332 are rusty as they have yet to be polished by train movement.







(a)



(b)













(a)



(b)























